

Mitsubishi Motors Australia Ltd.

Ann Sa Coo Iniz 309 South Australia Regional Offica 1284 South Road, Clowally Park South Australia S042 PO Box B, Melrose Park South Australia S039 24/7 Customer Assist +61 1300 13 12 17

love that car

April 2012

General Letter GL-12-005

To:Service Managers (cc Dealer Principals)Subject:MUT- III ECU Reprogramming Data CD-ROM Update - Version "CD 3A12041".

The purpose of this letter is to advise of the latest MUT-III ECU Reprogramming Data CD-ROM Update CD 3A12041

This CD-ROM will update MUT-III to include the latest modified reprogramming data for:

- Pajero 4M41 5AT body resonance whilst driving in 5th gear see NT 23-001
- ASX 4N13 6MT engine oil dilution, DTC P252F stored see XA 13-002
- Triton/Challenger 4D56 DTC P0299 Underboost see MN 13-009 & PB 13-002

Refer to Hotline Fix for details of repair procedures.

The CD-ROM enclosed with this letter contains the reprogramming data necessary for the successful update to the MUT-III reprogram database file to version number "CD 3A12031".

BEFORE PROCEEDING ANY FURTHER

ENSURE the MUT – III has been updated to PRA11121 (Refer General Letter GL-12-001). CD 3A12041 will not load unless the MUT – III has been updated

Check that the number on the ECU reprogramming update disc is "CD 3A12041".

TO PROCEED WITH UPDATE

Once you have confirmed the version number of your CD-ROM is correct, you can proceed with installing the MUT-III ECU Reprogramming Data.

Copyright © Mitsubishi Motors Australia Limited Please note:

1: The information contained in this document is CONFIDENTIAL and intended for Mitsubishi Dealer use only. It must not be provided to third parties. 2: This General Letter forms part of the Service Procedure Manual.









 CAUTION! - You must close all applications before installation of the MUT-III ECU reprogramming data.
To complete the update process for "MUT-III", follow the attached "MUT-III ECU Reprogramming Data update procedure" fully.

Yours sincerely, Mitsubishi Motors Australia Limited

D. R. Budden

National Service Manager



mitsubishi-motors.com.au



MUT-III ECU REPROGRAMMING DATA UPDATE PROCEDURE

 Before attempting this procedure, please ensure the ECU Reprogramming Data update disc you have received matches the version number "CD 3A12031".

NOTE:

- Ensure your computer is turned on before attempting to update the MUT-III.
- Ensure the V.C.I is not connected to the MUT-III.

1. UPDATING THE MUT-III ECU Reprogramming Data.

- **1.1** Insert the ECU Reprogramming Data update disc "CD 3A12041" into the CD ROM drive.
- **1.2** The "ECU Reprogramming update" dialogue box will appear automatically (*approx.10-20 secs.*) on the screen. Select "YES" in the dialogue box (Figure 1) to start installation of the reprogramming data.

ECU Reprogramming update 🛛 🗙	
•	ECU Reprogramming data update?
	Yes No

- **1.3** The data update will take approximately 30 seconds to complete.
- **1.4** When the **"ECU reprogramming update"** dialogue box appears select the **"OK"** button and then remove the reprogramming data CD from the CD-ROM drive.
- **1.5** The MUT-III ECU Reprogramming Data update is now completed.

Figure 1